


Chiswick Baths

Beach grade:



Chiswick Baths is a netted swimming enclosure in Five Dock Bay and is backed by a narrow sandy beach and a park.

The Beach Suitability Grade of Good indicates microbial water quality is considered suitable for swimming most of the time but can be susceptible to pollution after rain, with several potential sources of faecal contamination including upstream sources in the Parramatta River.


Enterococci levels increased with increasing rainfall, occasionally exceeding the safe swimming limit after no rain, and regularly after 10 mm or more.

The site has been monitored since 1999.


See 'How to read this report' for key to map.

Site type	Assessment period	Dry weather samples suitable for swimming	Water samples	Beach grade status
Estuarine	Oct 2017 to Apr 2020	97%	100	Stable


Sanitary inspection: Moderate



Microbial Assessment Category: B



Dry and wet weather water quality



Water quality in response to rainfall

