

# Cabarita Beach

Beach grade:



Cabarita Beach is a 120 metre long sandy beach and is backed by parklands.

The Beach Suitability Grade of Good indicates microbial water quality is considered suitable for swimming most of the time but can be susceptible to pollution after rain, with potential faecal contamination from sewage overflows and upstream sources in the Parramatta River.


Enterococci levels increased with increasing rainfall, occasionally exceeding the safe swimming limit in response to light rain, and often after 10 mm or more.

See 'How to read this report' for key to map.


The site has been monitored since 1996.

Site type	Assessment period	Dry weather samples suitable for swimming	Water samples	Beach grade status
Estuarine	Oct 2017 to Apr 2020	97%	100	Stable


## Sanitary inspection: Moderate



## Microbial Assessment Category: A



## Dry and wet weather water quality



## Water quality in response to rainfall

